

Release Notes

Applicable To

Efficient Networks SpeedStream 5660 Software

SUBJECT: Point Release of 5660 Router 2.3

1. Product Description

SpeedStream 5660 Software is updated to enhance the operation of SpeedStream products.

2. New Product Code

3. Old Product

4. Associated Products or Changes Affected

SpeedStream 5000 series products.

5. Change Classification

Critical
Service affecting

Important
Issues related

Nominal
Non service affecting

FYI
No Impact to network

6. Classification Substantiation

7. Reason for Change

Customer and partner feedback have identified items that are deemed highly desirable and have been incorporated into the software.

8. Description of Change

The SpeedStream 5660 software to be released to incorporate customer requests.

ADDED FEATURES

- Added PPTP to PPPoA support/PPTP relay
- Added ALG support for:
 - a) Microsoft Netmeeting
 - b) MSN Messenger
 - c) AOL Instant Message
 - d) Buddy Phone
 - e) ICQ 2000 (or latest version)
 - f) ICU II
 - g) MIRC
 - h) Net 2 Phone
 - i) CUSeeMe

- j) StarCraft
 - k) Rainbow Six
 - l) CounterStrike
 - m) Diablo 2
 - n) Half-Life
 - o) Quake III
 - p) Soldier of Fortune
 - q) Battle.net
 - r) Real Audio
 - s) Real Video
 - t) Microsoft Media Player
- Add IPSEC Pass through.

ISSUES FIXED

- Fixed FTP Client/Server; WAN access fixed
- Ability to support VPI, VCI of 1 and 1.
- Repaired PPPoE Authentication; fixed “bad authentication” error.
- Updated user sar_850 receiver driver.

KNOWN ISSUES

- Unable to map multiple hostnames to a single IP Address (cname/alias).
- Maximum configurable static entries in DNS Table is 64, gives error on 65th entry.
- Alignment errors need to be relabeled as length errors on the stats output.
- Gives immediate change choice to implement changes now or after reboot.

9. Effect of Change

10. Material Affected

N/A

11. Documentation Affected

All Product Documentation related to the SpeedStream Software has been updated to reflect the changes.

12. Supplier Implementation Date

The implementation date varies. All existing inventory will be consumed.

13. Modification Completion Date



Date: 08/30/01

(972) 852-1000 Phone

(972) 852-1001 Fax

N/A

14. Modification Location

Customer Premises if desired

15. Modification Cost

There is no cost to the customer for upgrading to the latest version of the SpeedStream software.

16. Attachments

NA

17. Comments

Existing installations do NOT require migration to the latest version of the SpeedStream software.

18. Requests for Technical Information

See your Efficient Sales professional for more information.